

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF MEMO TO FILE

DATE May 26, 1980

DEPARTMENT


Re: Gasoline Spill at Sunshine Street and Fort Avenue.

At approximately 9:00 P.M. on May 23, 1980, I received a report of a gasoline spill at Harold Peck's 66, 1211 W. Sunshine. Upon investigation it was found that the no lead underground storage tank had been overfilled. When I arrived at the scene Mr. Jim Cottengim, fireman, informed me that approximately 100 gallons of gasoline had been lost. He stated that they had flushed the area with a least 2000 gallons of water. The gasoline and water went into a dry ditch on Elfen Dale's property where it was allowed to evaporate. It did not appear that any of the gasoline reached Fassnight Creek.

Mr. Dale Peterson, driver for Ellex Transportation, told me that he had over-filled one of the storage tanks and that he lost approximately 35-50 gallons. Ellex Transportation is out of Tulsa, Oklahoma but the truck was leased to Harold Anderson. Mr. Peterson was informed of his need to report the spill to the proper authorities.

1211 W. Sunshine

SIGNED *Gene Pabst*
Water Pollution Control Inspector III
Surveillance and Enforcement



1211 W. Sunshine

October 20, 1983

Mr. Robert Boyar
Webster Companies
2400 E. Bennett
Springfield, MO 65804

Dear Mr. Boyar:

As you know, for the past month the City of Springfield has been experiencing a problem of flammable hydrocarbon products entering its sanitary sewer system in the 1600-1800 block of south Fort, that were traced to a leaking regular tank and gasoline line at Harold Peck's 66 Station at 1211 W. Sunshine. The fuel tanks and lines are owned by Webster Companies. You had the fuel lines and tanks tested as we requested and you replaced all of the fuel lines.

Because we are still detecting dangerously high levels of flammable hydrocarbon products in the sanitary sewer, especially after rainfall events, this department is requiring you to dig an interceptor trench and install a recovery well between Harold Peck's 66 Station and the house at 1754 S. Fort. This should be completed before November, 1983.

Enclosed is a suggested design for the trench and well taken from the American Petroleum Institute's Underground Spill Cleanup Manual.

Due to the nature of the problem, further action may be required to protect the health, life, and property of those affected by the migration of the lost product.

If you have any questions, please don't hesitate to call.

Yours truly,

Karen A. Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

KAC:js

cc: Robert R. Schaefer, P.E., Superintendent of Sanitary Services
Henry Cole, Sanitary Engineer
Greg Perkins, Dept. of Natural Resources
Dale Bittle, Chief Fire Marshall
File

1211 W. Sunshine

generally applicable to crude oils. Not all of the specification tests are of importance in a spill situation. However, the series of methods for the analysis of waterborne oils is particularly appropriate to the identification of unknown oils.

The second series of methods particularly applicable to unknown oils is in the U.S. Coast Guard's *Oil Spill Identification System* (Report No. CG-D-52-77). Some of these methods are similar to those in the ASTM Standards on waterborne oils; however, the report also contains some more elaborate techniques.

V. CLEANUP TECHNIQUES

After a spill or leak has been absorbed into the ground, a recovery system may be used to remove the product. Because many conditions affect migration and recovery of product, no single system works in all or even most cases. Therefore, recovery systems usually must be tailor-made for a particular spill or leak. As techniques for locating, containing and recovering free-floating product on the water table are extremely complicated, it is strongly recommended that recovery projects be directed by someone trained and experienced in this work.

5.1 Test Wells

Once it is known that product has reached the water table, the extent of the contamination and its potential environmental and safety hazards should be determined by drilling a series of test wells. The effectiveness of cleanup operations is greatly increased by establishing the area's soil characteristics, water table depth and gradient.

The first few test wells should be located near the probable source of the spill. Also, wells should be located near an affected area; for example, near a house with gasoline in the basement. If a test well reveals contamination, others must be drilled farther out, until the area of contamination can be fairly well defined. In large concentrated spills, the areas sloping upstream or to the sides of the spill should be investigated, since mounding of product can cause uphill migration. Site conditions may suggest other areas for test wells.

After a series of test wells has defined the scope of the contaminated area, it must be monitored periodically for product thickness and for spread of contamination. When necessary data on the spill area have been accumulated, a recovery plan can be devised.

5.2 Interceptor Trenches

Many spills into the ground encounter a high water table, impervious soil or a rock layer and remain near the surface. These spills may be contained and recovered with a trench, ditch or drain system designed to intercept the product (Figure 12).

In a shallow spill, it is normally possible to respond more rapidly and effectively with an interceptor trench or drain than by using a well system, since equipment and contractors for this type of installation are readily available in most areas and the recovery techniques are less complicated.


Trench-type recovery systems are generally limited to depths of six to 10 feet. Depths greater than these may be impractical due to soil conditions, the capabilities of normally available excavating equipment and the large amount of soil which must be removed.

A ditch should be constructed across the entire front of the migrating body of oil. If product has entered a confined structure such as a building or sewer, the trench should be dug as close as possible to the structure without damaging its basement or foundation.


If soil conditions will permit, ditches should be kept as narrow as the bucket on the excavating equipment, and should be constructed to a depth of one to four feet below the water table surface. The downstream wall should be lined with an impermeable material such as polyethylene film (Figure 12) to block floating oil but permit water to pass below. The barrier material should be placed a minimum of a few feet above the product level and a minimum of one foot below the oil/water interface. If the ditch will be used as a withdrawal point to lower the water table, the barrier must be situated deep enough to intercept the product at the lowest drawdown level. As it usually is advisable to fill the ditch with coarse material, such as crushed stone or gravel, the film must be of sufficient strength to prevent puncture or tearing.

One or more randomly slotted culvert pipes, or similar material wrapped with plastic window screening, should be lowered to the bottom of the trench. The bottom of the culvert should be capped to prevent silt build-up. Once the culvert is in place, the ditch should carefully be filled to within two feet of the native ground surface with a very porous material, such as crushed stone or gravel. Soil should then be used to fill the remainder of the trench.

Groundwater can be removed from the trench to influence the flow of product, or—if left open—the trench



PLAN VIEW



CROSS SECTION

Figure 12 — Interceptor Trench

can serve as a collection point for skimming. It is important to note that pumping or skimming must be continuous, or collected oil will tend to move to the ends of the ditch and pass around the barrier.

If an open trench is used to contain a spilled product on the water table, all safety precautions must be taken to eliminate the possibility of explosion or fire. Safety precautions must also be observed when selecting pumping equipment for use in flammable liquids or vapors.

5.3 Pumped Trenches

The installation of a pumped intercepting system will increase the area of influence of the collection trench by lowering the water table, thus increasing the rate of recovery. Pumping to lower the water table can create excessive amounts of waste water which may be contaminated by the spill. Therefore, before installing pumped systems, it should be considered whether treatment and disposal are feasible and permissible.

Construction procedures for pumped trenches or drain systems are similar to those for gravity drainage. The primary difference is that the interceptor trench or drainage pipe needs to be excavated to greater depth to allow for the lowering of the water table. This system can be designed to automatically maintain a constant water table within the trench for collecting, containing and skimming the migrating oil running into the interceptor trench.

When it is determined that a pumped interceptor system may be required, a knowledgeable and experienced contractor should be consulted on its design and installation.

5.4 Well Systems

Mobile product will normally be better contained and recovered with properly designed continuous-pumping recovery wells. They can be designed with the proper size, depth and pumping rate to create an adequate cone of depression in the water table thereby containing the oil and influencing its flow to the recovery point.

If the water table is nearly horizontal, a shallow depression will suffice to confine the floating product. If the water table is inclined, as is common, the cone must be deep enough to reverse the gradient. The point at which the reversal occurs, called the "divide," must lie beyond the contaminated area in order to contain the oil.

Once a well is installed, a depression cone of considerable extent normally can be created in a matter of minutes or hours. In most cases, this is enough time to install a recovery system before mobile product can be

carried out of reach by moving groundwater. The importance of the drawdown in relation to the gradient also must be kept in mind (see Figure 13).

Although a cone of depression can be maintained by continuous pumping with one pump situated below the surface of the water table, floating oil will not be recovered unless it is drawn down to the pump's withdrawal point. It is, therefore, important when using a single recovery pump to locate it at a depth where it will both lower the water table and skim collected product. As a minimum, the effluent from such a system must be directed into an oil/water separator. At times, it may be necessary to set two or more separators in series to allow for further water purification. In some cases involving badly contaminated groundwater, additional treatment of produced water will be necessary prior to discharge.

As a rule, it is better to use two pumps instead of one—a pump to maintain the cone and a smaller one to pump the contaminant from the surface of the water. This arrangement reduces or eliminates the volume of fluid which must be separated for proper disposal. This also allows pumping of noncontaminated groundwater to a point of free discharge.

Depending on the seriousness of the spill, pumping may be required for an extended period of time. Ideally, pumping should continue through several fluctuations of the water table and should be abandoned only after the mobile product has been reduced to an acceptable level.

Creation of an unnecessarily large cone of depression may result in contamination of the soil and water table to a greater depth. It will also produce an excessive volume of water.

Spills in a concentrated area where trenches or drains are not practical or desirable sometimes may be recovered by pumping from contaminated test wells. Periodic removal of product accumulated in these wells may be adequate to contain and recover the product. Pumping of the test wells can also create a cone of depression in the water table to increase the recovery rate.

5.5 Effects of Pumping

The objective of the drawdown well is to establish a depression in the water table that prevents the oil from spreading and concentrates it for removal. The rate at which fluid is withdrawn and the permeability of the soil determines the size and rate of development of the depression.

Since permeability varies, the depression-forming process is different in all areas. When enough informa-

November 16, 1983

Certified No. PO4 9037038

Mr. Robert Boyar
Webster Companies
2400 E. Bennett
Springfield, MO 65804

Dear Mr. Boyar:

Due to the large amount of rainfall the city has received in the past month, the two recovery wells that were installed in the interceptor trench at Harold Peck's 66 station at 1211 W. Sunshine have water standing in them. The explosion meter reading in both of these wells is 50% of the Lower Explosion Limit (L.E.L.). It is important to pump out these wells occasionally or the hydrocarbon product will move to the ends of the ditch, pass around the impermeable barrier and enter the city's sanitary sewer system.

It is our recommendation that you check these wells at least twice a month. When water is standing in the wells they should be pumped out with an explosion-proof pump and the hydrocarbon product skimmed off for disposal in an approved manner.

If you have any questions, please don't hesitate to call 864-1924.

Yours truly,

Karen Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

KC:js

cc: Robert R. Schaefer, P.E., Superintendent of Sanitary Services
Henry Cole, P.E., Sanitary Engineer
Greg Perkins, Department of Natural Resources
Dale Bittle, Chief Fire Marshall
File

1211 W. Sunshine

STODDARD EQUIPMENT CO.

LP Gas and Service Station Equipment

Sales and Service

3536 E. SUNSHINE SPRINGFIELD, MISSOURI 65804

Nov. 22, 1983

Department of Public Works
Attn: Karen A. Chandler
830 Boonville Ave
Springfield, Mo. 65802

Dear Ms. Chandler

This letter is to certify that we have tested and repaired leaks at the Phillips Service Station at Sunshine and Fort streets.

Our initial tests found leaks in the west 4,000 gallon regular storage tank, the no lead product line, and the diesel vent line. All other lines and tanks checked OK at 4 p.s.i. on tanks and vent lines and 70 p.s.i. on product lines.

We, at the expense of Webster Oil Co. replaced the regular and no lead product lines complete and replaced the west regular tank. Webster Oil Co. decided to replace the regular product line even though it did not leak to insure a future problem of this same type would not occur due to the line being of same age as the ones that failed.

All new lines and the tank were air tested and inspected by the local Fire Marshals after installations were completed.

If I can be of any further help, feel free to call.

Sincerely

W. O. Hawkins Jr.

W.O. Hawkins, Jr.
Assistant Manager

cc Jack Webster III
Bob Boyar

1211 W. Sunshine

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE 11-7-83

DEPARTMENT _____

On Tuesday, September 27, 1983, Bill West reported a strong gasoline odor in the sewer at Fort and Stanford. The explosion meter read 100% of L.E.L. at manhole 12 and 30% of L.E.L. at manhole 22 on Fort Street. Various other manholes were checked visually and with the meter in order to determine the source of the leak. The results were:

<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
Sunshine	1	0
University	17	5
"	18	0
"	19	0
Stanford	27	0
Fort	21	5

Harold Peck, of Harold Peck's Phillips 66 station at 1211 W. Sunshine, said that last week he had noticed they were pumping air through the dispensers on the regular pumps. David Reeves, of Stoddard Equipment, said they had tested the regular line Monday and it wouldn't hold pressure. The line was rubber and had been in the ground 15-20 years. Stoddard found a hole in the line to the regular pump and they replaced that section of the line. On Tuesday they air tested the line again and for 4½ hours at 60 lbs. of pressure, and it didn't lose a pound of pressure.

Omer Boyce flushed the lines that run into manhole 12 on Fort Street twice. The night crew flushed these lines once each shift. The covers on manholes 12 and 22 on Fort Street were left off overnight to vent off the gasoline vapors.

Wednesday, September 28, 1983:

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:00 a.m.	Fort	12	20
3:00 p.m.	"	12	100

Omer Boyce flushed the lines going into manhole 12 on Fort and the night crew flushed these lines once each shift.

Thursday, September 29, 1983:

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:00 a.m.	Fort	12	15
1:30 p.m.	"	12	100
2:30 p.m.	"	12	100

Fire Marshall Dave Wilson also got 100% of L.E.L. at manhole 12 at 2:30 p.m. I met with Ray Toates of City Utilities to borrow a water meter so that we can flush the line continuously from the fire hydrant east of manhole 19 on west University Street. Gene Pabst, J.D. Slaughter and I set up the fire hoses and began flushing the line. The City Utilities meter is a Worthington-Gamon meter. The beginning reading was 0000740cf.

I asked Harold Peck to have all of the tanks and lines tested. He said he would call the owner (Webster Oil Company) in the morning and have it done. The manager at Taylor Express Mart at 1201 West Sunshine was gone for the day and I was unable to talk to her at this time.

SIGNED _____

1211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE 11-7-83

DEPARTMENT _____

Mrs. Deeds, at 1650 S. Fort, had called to report a gasoline odor in her bathroom, but it was gone when I got there. She told me that she had smelled the odor on and off since July.

I called the telephone company to report that we had gasoline in the sewer and probably in the ground because they have buried cables in this area.

Friday, September 30, 1983:

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
5:00 p.m.	Fort	12	30
	"	17	40
	"	21	20

I talked to Bob Boyar of Webster Oil Companies and he said he would have the tanks and lines tested on Monday. The residents of 1754 S. Fort complained of a gasoline odor in their house, so I asked Ralph Whitworth to flush the line between manholes 17 and 21 on Fort.

Saturday, October 1, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
8:30 a.m.	University	17	50
	"	18	<10
	Fort	12	40

I asked Gerald Noblett to have a crew flush between manholes 17 and 21 on Fort and opened up the cover of manhole 21 to allow the gasoline vapors to vent off.

Sunday, October 2, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:30 p.m.	Univerity	17	30
	Fort	12	30
	"	21	50

Monday, October 3, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:00 a.m.	Stanford	22	10
	Fort	12	30
	"	21	40
	University	17	15

Fire Marshall Jim Dancy also called Bob Boyar over the weekend and asked him to have all the lines and tanks tested.

I talked to Sharon Jones, the manager at Taylor Express Mart (Taylor Petroleum), and she hasn't noticed any product loss. They have three tanks: regular, no lead, and premium. The regular tank was put in about a year ago and holds 8,000 gallons of gasoline. There is an abandoned tank on the west side of her property. The tank had about 1" of water in the bottom of it and 100% of L.E.L. on the explosion meter. I told her she needed to contact a fire marshall to find out the procedure for abandoning a tank.

SIGNED _____

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM


ATTENTION OF FILEDATE 11-7-83

DEPARTMENT _____

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:30 p.m.	Fort	21	15

One of the residents in the house at 1754 S. Fort said the odor wasn't as strong in the house.

One of the Stoddard Equipment operators said it might be two or three days before they would have any results as the cement on the top of the tanks had to be jack-hammered off.



Tuesday, October 4, 1983
It rained all night.

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:30 a.m.	Fort	12	80
"	"	21	50
2:45	Stanford	22	0
	Fort	12	25
	"	21	5

It started raining again about 2:30 p.m.

Wednesday, October 5, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:40 a.m.	Stanford	22	10
	Fort	12	40
	"	21	5

The siphon birdge between the two regular tanks was a rubber hose. There were no apparent leaks in the hose but Stoddard Equipment replaced it.

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:00 p.m.	Stanford	22	5
	University	17	0
	Fort	12	80
	"	21	0

I gave Dave Reeves of Stoddard Equipment my card and asked him to send me the results of his tests when he's done.

Thursday, October 6, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:00 a.m.	Stanford	22	40
	University	17	50
	Fort	12	75
	"	21	50

Dave Reeves said they put pressure on one of the regular lines last night and it didn't hold. He wasn't sure if the problem was in the tank or the vent line.

SIGNED _____

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF FILEDATE 11-7-83

DEPARTMENT _____

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:00	Stanford	22	0
	Fort	12	60

I called Jim Dancy about an interceptor trench, but he said the fire department couldn't make that kind of recommendation.

Friday, October 7, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
11:00 a.m.	Stanford	22	0
	University	17	35
	Fort	12	30
	Fort	21	35

Dave Reeves said that the diesel tank wouldn't hold pressure, but sticking the tank didn't indicate a product loss.

12:00 p.m. Bob Boyar went to the station to shut down all of the dispensers and I met with him at this time. I reminded him that Webster Oil Company was liable for any problems caused by hydrocarbon products in the sewer and recommended that he build an interceptor trench with a recovery well and gave him a copy of the section on interceptor trenches in Chapter V "Clean-Up Techniques" in the Underground Spill Cleanup Manual published by the American Petroleum Institute. At this time, he said that he would dig a trench and that he might get rid of the tanks altogether. He didn't know how much product had been lost.

4:00 p.m. I called Bob Boyar at work and he said that he was having all of the gasoline removed from the tanks, while Stoddard Equipment finished testing them. At this time he said he wouldn't dig a trench, but would take core samples.

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:30 p.m.	Stanford	22	0
	University	17	20
	Fort	12	0
	"	21	45

Saturday, October 8, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:30 p.m.	Standord	22	0
	University	17	20
	Fort	12	30
	"	21	15

Sunday, October 9, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
7:00 p.m.	Stanford	22	0
	University	17	15
	Fort	12	15
	"	21	15

SIGNED _____

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE 11-7-83

DEPARTMENT _____

Monday, October 10, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:30 a.m.	Stanford	22	0
	University	17	30
	"	18	0
	Fort	12	10
	"	21	30

2:30 p.m. The diesel tank wasn't leaking, the leak was in the vent line, they were still testing the regular tanks.

Tuesday, October 11, 1983

Dave Reeves of Stoddard Equipment said that the west regular tank wouldn't hold pressure. This tank was buried in lime chat which is very corrosive. The no lead line wouldn't hold pressure. Dave said they would replace all of the lines, replace or abandon the regular tank and the service station would probably be back in business by the weekend.

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:00 p.m.	Stanford	22	40
	University	17	30
	"	18	0
	Fort	12	40
	"	21	25

It started raining hard shortly after 4:00 p.m.

Wednesday, October 12, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:00 p.m.	Stanford	22	15
	University	17	5
	Fort	12	15
	"	21	<5

Stoddard Equipment was replacing all of the lines.

Thursday, October 13, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
11:00 a.m.	Stanford	22	0
	University	17	25
	"	18	100
	Fort	12	<5
	"	21	5
	Sunshine	45	0
	"	19	0
	"	19a	0

Friday, October 14, 1983

<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
Stanford	22	0
University	17	40
"	18	0
Fort	12	20
"	21	35

SIGNED _____

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____
 DEPARTMENT _____

DATE 11-7-83

Dave Reeves of Stoddard Equipment said that new fuel lines were pressure tested section by section and the Fire Department inspected the lines.

Saturday, October 15, 1983

<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
Stanford	22	0
University	17	40
"	18	0
Fort	12	35
"	22	35

Sunday, October 16, 1983

<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
Stanford	22	30
University	17	30
"	18	0
Fort	12	50
"	21	0

It rained all night and day.

Monday, October 16, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:30 a.m.	Stanford	22	0
	University	17	50
	"	18	0
	Fort	12	50
	"	21	25

Tuesday, October 18, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
1:30 p.m.	Stanford	22	0
	University	17	50
	"	18	0
	Fort	12	50
	"	21	25

I talked to Bob Boyar on the phone. He said they lost approximately 800 gallons of product. I recommended that he report the loss to the Missouri Department of Natural Resources.

At this time he thought he would abandon the leaking tank, and I advised him to contact the fire marshall about the procedure.

They were waiting for an agent from Phillips 66 to inspect the station and advise them about clean up procedure.

SIGNED _____

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF FILEDATE 11-9-83DEPARTMENT

Wednesday, October 19, 1983

<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
Stanford	22	<5
University	17	35
"	18	0
Fort	12	50
"	21	20

Thursday, October 20, 1983

<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
Stanford	22	<5
University	17	35
"	18	0
Fort	12	35
"	21	35

I sent a letter to Bob Boyar, of Webster Petroleum, requiring them to dig a trench by November 1, 1983.

Friday, October 21, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
5:45 p.m.	Stanford	22	0
	University	17	5
	"	18	100
	Fort	12	0
	"	21	0

I reported the 100% of L.E.L. in manhole 18 to the Fire Department.

Saturday, October 22, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:30 p.m.	Stanford	22	0
	University	17	30
	"	18	5
	Fort	12	0
	"	21	<10

Sunday, October 23, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:30 p.m.	Stanford	22	0
	University	17	15
	"	18	0
	Fort	12	0
	"	21	<5

SIGNED _____

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF FILEDATE 11-9-83DEPARTMENT

Monday, October 24, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:30 a.m.	Stanford	22	0
	University	17	15
	"	18	0
	Fort	12	0
	"	21	<10

Turned off water, the meter read 0431810

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:00 p.m.	Stanford	22	0
	University	17	5
	"	18	0
	Fort	12	0
	"	21	5

Tuesday, October 25, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:30 a.m.	Stanford	22	<5
	University	17	20
	"	18	0
	Fort	12	10
	"	21	0
3:15 p.m.	Stanford	22	<5
	University	17	<10
	"	18	0
	Fort	12	<15
	"	21	0

Wednesday, October 26, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:00 p.m.	Stanford	22	0
	University	17	<5
	"	18	45
	Fort	12	<5
	"	21	0

Thursday, October 27, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:30 a.m.	Stanford	22	0
	University	17	30
	"	18	0
	Fort	12	0
	"	21	20

SIGNED

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF FILEDATE 11-9-83DEPARTMENT

I talked to Bob Boyar, of Webster Oil Company, on the phone to see if he had any questions about my letter. He said he will dig an interceptor trench Monday or Tuesday. His estimate of product loss was between 700-800 gallons. He said that Harold Peck owned that gasoline and didn't keep complete inventory records. Bob said that in the future he will check the records twice a week.

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:00 p.m.	Stanford	22	15
	University	17	45
	"	18	10
	Fort	12	0
	"	21	0

Water was turned on again. The resident of 1736 S. Fort said she could smell gasoline in her house at times, particularly at night.

Friday, October 28, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
11:00 a.m.	Stanford	22	0
	University	17	15
	"	18	20
	Fort	12	0
	"	21	<5

Saturday, October 29, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
5:30 p.m.	Stanford	22	<15
	University	17	10
	"	18	0
	Fort	12	10
	"	21	10

Monday, October 31

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:15 a.m.	Stanford	22	10
	University	17	10
	"	18	0
	Fort	12	5
	"	21	<10
3:00 p.m.	Stanford	22	10
	University	17	15
	"	18	0
	Fort	12	20
	"	21	15

Stoddard Equipment started their trench. At the deepest spot, approximately 13 ft. down, there was a weak gasoline odor and the dirt was damp looking.

SIGNED

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE 11-22-83

DEPARTMENT _____

Saturday, November 5, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:00 p.m.	Stanford	22	5
	University	17	5
	"	18	0
	Fort	12	0
	"	21	5

Sunday, November 6, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:00 p.m.	Stanford	22	5
	University	17	10
	"	18	0
	Fort	12	0
	"	21	10

Monday, November 7, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:00 p.m.	Stanford	22	<5
	University	17	15
	"	18	0
	Fort	12	0
	"	21	<5

Stoddard Equipment began digging up the old tank.

Tuesday, November 8, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:20 a.m.	Stanford	22	0
	University	17	5
	"	18	0
	Fort	12	0
	"	21	5

I turned off the fire hydrant (reading 0454390)

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:00 p.m.	Stanford	22	0
	University	17	15
	"	18	0
	Fort	12	5
	"	21	10

Stoddard had the old tank out. There was a gasoline odor in the pit where the tank had been. There appeared to be a piece of clay tile on the west side of the pit.

Wednesday, November 9, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:30 p.m.	Stanford	22	0
	University	17	15
	"	18	15
	"	19	10
	Fort	12	0
	"		

SIGNED _____
21 0

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE 11-22-83

DEPARTMENT _____

Stoddard Equipment put the new tank in.

Thursday, November 10, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:45 a.m.	Stanford	22	0
	University	17	10
	"	18	20
	"	19	<10
	Fort	12	0
	"	21	0

Friday, November 11, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:15 p.m.	Stanford	22	0
	University	17	10
	"	18	0
	"	19	0
	Fort	12	0
	"	21	10

Saturday, November 12, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:15 p.m.	Stanford	22	0
	University	17	<10
	"	18	0
	"	19	0
	Fort	12	0
	"	21	10

Sunday, November 13, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
1:00 p.m.	Stanford	22	0
	University	17	<25
	"	18	0
	"	19	0
	Fort	12	0
	"	21	10

The batteries in the explosion meter were weak.

Monday, November 14, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:45 p.m.	University	17	15
	"	18	0
	Fort	12	20
	"	21	<10

We removed hose and stand.

SIGNED _____

CITY OF SPRINGFIELD INTER-OFFICE MEMORANDUM

ATTENTION OF FILE
DEPARTMENT

DATE 11-22-83

Tuesday, November 15, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:15 p.m.	University	17	5
	"	18	10
	Fort	12	0

Friday, November 18, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:30 p.m.	Stanford	22	15
	University	17	30
	"	18	0
	"	19	0
	Fort	12	0
	"	21	15

Bob Corson and I set up the meter and fire hose again and started flushing. Beginning reading was 0481710. Mrs. Green at 1128 University complained about the hose being set up again.

Saturday, November 19, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:00 p.m.	Stanford	22	5
	University	17	10
	"	18	0
	"	19	0
	Fort	12	5
	"	21	10

Sunday, November 20, 1983

Meter not working.

Monday, November 21, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:35	Stanford	22	0
	University	17	<10
	"	18	0
	"	19	0
	Fort	12	0
	"	21	<10

Gene Pabst and I turned the meter off again. Ending reading 0484020.

SIGNED Karen Chandler

February 13, 1984

Certified No. PO4 9037040

Mr. Jack Webster III, President
Webster Companies
2400 East Bennett
Springfield, Missouri 65804

1

Re: Harold Peck's 66
1211 W. Sunshine

Dear Mr. Webster:

On Tuesday, September 27, 1983, personnel from the City of Springfield's Water Pollution Control Section, Surveillance and Enforcement Branch, received a report of flammable hydrocarbon products entering the City's sanitary sewer system in the 1600-1800 block of South Fort. The hydrocarbon products were traced to Harold Peck's 66 service station at 1211 W. Sunshine. The tanks and fuel lines are owned by Webster Companies. You had the fuel lines and tanks tested as the City requested by Stoddard Equipment Company. As you know, leaks were found in the west regular storage tank, the no lead product line and the diesel vent line.

The ordinances of the City of Springfield provide for the recovery of the costs involved in the abatement of a violation under emergency conditions. By means of a copy of this letter, these costs are being certified to the Director of Finance as true and accurate costs incurred by the City of Springfield.

Attached to this letter is a detailed explanation of the costs incurred by the Water Pollution Control Section in the detection, monitoring, and treatment of flammable hydrocarbon products that have entered the City of Springfield's sanitary sewer system to November 29, 1983. Payment of these costs should be made to the City of Springfield, and sent to:

City of Springfield
City Hall, Room 210
830 Boonville
Springfield, MO 65802
Attention: Mr. Robert Schaefer

1211 W. Sunshine

Mr. Jack Webster III, President
February 13, 1984
Page 2

Due to the nature of the problem further action may be required to protect the health, life and property of those affected by the migration of lost hydrocarbon product.

Enclosed, please find a copy of Chapter 30 of the Springfield City Code. If you have any questions, please don't hesitate to call.

Yours truly,

Karen Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

KC:js

Enclosure

cc: Robert R. Schaefer, P.E., Superintendent of Sanitary Services
Greg Perkins, Missouri Department of Natural Resources
Dale Bittle, Chief Fire Marshall
File

1211 W. Sunshine

WATER AND SEWER COSTS:

September 27, 1983 to November 29, 1983

Water - 4560 ccf	1,922.55
Sewer - 4560 ccf @ .46/ccf	2,097.60
" - (Basic customer charge)	6.04

PERSONNEL COSTS: Surveillance & Enforcement

September 27, 1983 to November 29, 1983

	Burden Rate	Overtime Rate	Time at Site	Costs
Chandler	14.39		31.75	456.88
"		21.58	44.00	949.52
Corson	17.23		13.25	228.29
Pabst	17.23		5.25	90.46
Slaughter	14.39		.50	7.20
Short	14.39		.50	7.20

EQUIPMENT COSTS

Flusher (1 a crew of 3)	4.5 hrs. @ 59.29/hr.	311.76
P2-15		
P2-22	462 miles @ .35/mi.	<u>161.70</u>
P2-24		

TOTAL COST:

\$6,239.20

1211 W. Sunshine

Copy to Mr. Carson 12/16/00. No. 65502

Petro Tite
TANK TESTER

HEATH
CONSULTANTS
100 TOSCA DRIVE

14. Webster O.I. Co. N. Kansas Springfield, Missouri 65502
Name of Supplier, Owner or Dealer Address No. and Street(s) City State Date of Test

15. TANK TO TEST South Tank of 4 Identity by position Premium Unleaded Brand and Grade

16. CAPACITY Nominal Capacity 4000 Gallons By most accurate capacity chart available 3676 Gallons Is there doubt as to True Capacity? ☒ See Section "DETERMINING TANK CAPACITY"

From Station Chart ☒ Tank Manufacturer's Chart Company Engineering Data Charts supplied with Petro Tite AUG 4 1986

17. FILL-UP FOR TEST Slick Water Bottom before Fill-up 0 to 1/8 in. 0 Gallons Inventory 3626 Stick Readings to 1/8 in. Gallons Total Gallons ea. Reading 3682

FILL UP, STICK BEFORE AND AFTER EACH COMPARTMENT DROP OR EACH METERED DELIVERY QUANTITY

Tank Diameter 2' x 14' Product in full tank (up to fill pipe) 3682

18. SPECIAL CONDITIONS AND PROCEDURES TO TEST THIS TANK See manual sections applicable. Check below and record procedure in log (26).

☐ Water in tank ☐ High water table in tank excavation ☐ Line(s) being tested with LVLT API Corrective = 62.6

Temp. = 86°F VAPOR RECOVERY SYSTEM ☐ Stage I ☐ Stage II

19. TANK MEASUREMENTS FOR TSIT ASSEMBLY Bottom of tank to Grade* Add 30" for 4" L. Add 24" for 3" L or air seal. Total tubing to assemble Approximate

20. EXTENSION HOSE SETTING Tank top to grade* Extend hose on suction tube 6" or more below tank top

21. TEMPERATURE/VOLUME FACTOR (a) TO TEST THIS TANK Is Today Warmer? ☒ Colder? ☐ F Product in Tank 81°F Fill-up Product on Truck 81°F Expected Change (or -) digits 19000 80°F 81°F

22. Thermal-Sensor reading after circulation 19000 digits

23. Digits per °F in range of expected change 314 digits

24. 3682 total quantity in full tank (16 or 17) coefficient of expansion for involved product = 2.327

25. 2.327 volume change per °F (24) 314 Digits per °F in test Range (23) = 0074108 Volume change per digit. Compute to 4 decimal places. This is test factor (a)

26. LOG OF TEST PROCEDURES

27. DATE 28. Record details of setting up and running test (Use full length of line if needed.)

29. Reading No. Stanpipe Level in inches Beginning of Reading Level to which Restored

30. HYDROSTATIC PRESSURE CONTROL

31. VOLUME MEASUREMENTS (V) RECORD TO .001 GAL. Before Reading After Reading Product in Graduate Replaced (-) Product Recovered (+)

32. Product in Graduate

33. Thermal Sensor Reading

34. TEMPERATURE COMPENSATION USE FACTOR (a)

35. Change Higher + Lower - (c)

36. Computation (c) x (a) = Expansion + Contraction -

37. Temperature Adjustment Volume Minus Expansion (+) or Contraction (-) #33(V) - #37(I)

38. NET VOLUME CHANGES EACH READING

39. ACCUMULATED CHANGE At High Level record Total End Delinquency At Low Level compute Change per Hour (NFEA criteria)

Arrived at Location Tank Topped Off

1211 W. Sunshine

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF Robert Schaefer

DATE August 16, 1984

DEPARTMENT SANITARY SERVICES

With the payment of spill abatement/cleanup costs by Webster Companies for 1211 W. Sunshine and 1003 S. Glenstone, the following amounts are due City Utilities for hydrant water used to mitigate the problem.

1003 S. Glenstone, March, 1983

2,647 ccf

\$1167.88

1211 W. Sunshine, November, 1983

4,560 ccf

\$1922.55

Total Due - \$3,090.43

Remit payment to City Utilities, Attention Ms. Helen Spellman.

cc: File (2)

Stephen Short
Water Pollution Control Inspector II
Surveillance & Enforcement

Karen Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

1211 W - Sunshine

SIGNED

Rate effective 1-1-83 until April 14

4560	OC 7	
<u>5</u>	=	690
4555		
<u>95 @ 1.19</u>		113.05
4460		
<u>200 @ 1.00</u>		200.00
4260		
<u>300 @ .59</u>		177.00
3960	@ .36	1425.60
		<u>\$ 1922.55</u>

1211 W. Sunshine



May 3, 1984

Ms. Karen Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement
Department of Public Works
830 Boonville Avenue
Springfield, Missouri 65801

Dear Ms. Chandler:

Thank you very much for your April 20th letter concerning our difficulties at Harold Peck's 66. This claim has been turned over to Northwestern National for handling. As provided in our subrogation agreement with our insurer, we are unable to make payments or give information regarding any matter which is submitted to them for processing. Rest assured that the company is working on the matter and will take care of it as soon as possible. The City of Springfield should expect to have this amount paid within ninety days.

MAY 7 1984

We do apologize for the delay.

Sincerely,

A handwritten signature in dark ink, appearing to read "Jack Webster III", written over a horizontal line.

Jack Webster III

JIII:pf



2400 E. Bennett St. • P.O. Box 10466 • Springfield, MO 65808 • (417) 883-2666
Double J Ranches featuring Simmental & Performance Tested Beef Cattle



K.C. APR 27 1984

PS Form 3811, Apr. 1977

RETURN RECEIPT, REGISTERED, INSURED AND CERTIFIED MAIL

1. The following service is requested (check one).
☒ Show to whom and date delivered.
☐ Show to whom, date, and address of delivery.
☐ RESTRICTED DELIVERY
Show to whom and date delivered.
☐ RESTRICTED DELIVERY
Show to whom, date, and address of delivery. \$
(CONSULT POSTMASTER FOR FEES)

2. ARTICLE ADDRESSED TO:
Jack Webster, Webster Companies
2400 E. Bennett
Springfield, MO 65804

3. ARTICLE DESCRIPTION:
REGISTERED NO. CERTIFIED NO. INSURED NO.
P04 9037046

(Always obtain signature of addressee or agent)
I have received the article described above.
SIGNATURE ☐ Addressee ☐ Authorized agent

4. DATE OF DELIVERY

5. ADDRESS (Complete only if requested)

6. UNABLE TO DELIVER BECAUSE:

SPRINGFIELD, MO 65804
APR 24 1984
POSTMARK
CLEVER, MO 64734
APR 24 1984
INITIALS

☆ GPO: 1977-0-249595

P04 9037046

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED—
NOT FOR INTERNATIONAL MAIL
(See Reverse)

PS Form 3800, Apr. 1976

SENT TO		Jack Webster, Webster	
STREET AND NO.		2400 East Bennett	
P.O. STATE AND ZIP CODE		Springfield, MO 65804	
POSTAGE		\$	
CERTIFIED FEE		\$	
OPTIONAL SERVICES			
RETURN RECEIPT SERVICE			
SHOW TO WHOM AND DATE DELIVERED			
SHOW TO WHOM, DATE, AND ADDRESS OF DELIVERY			
SHOW TO WHOM, DATE AND ADDRESS OF DELIVERY WITH RESTRICTED DELIVERY			
TOTAL POSTAGE AND FEES		\$	
POSTMARK OR DATE			

April 20, 1984

Certified No. P04 9037046

Mr. Jack Webster III, President
Webster Companies
2400 East Bennett
Springfield, MO 65804

Dear Mr. Webster:

On February 13, 1984, the City of Springfield sent you a certified letter explaining the costs incurred in monitoring and flushing out the flammable hydrocarbon products that had entered the City's sanitary sewer system from Harold Peck's 66 service station at 1211 W. Sunshine. The station is owned by Webster Companies.

As explained to you in the above mentioned letter, Chapter 30, Section 30-18 of the Springfield City Code provides for the recovery of costs involved in the abatement of a violation under emergency conditions. The costs incurred by the City for abating the violation were \$6,239.20. As of this date the City has not received payment for these costs.

Please respond, in writing, within 15 days as to what provisions are being made for payment of this bill.

If you have any questions, please feel free to call at 864-1924.

Yours truly,

Karen Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

KC:js

cc: Mr. Robert R. Schaefer, P.E., Superintendent of Sanitary Services
Mr. Greg Perkins, Missouri Department of Natural Resources
Mr. Bob Handley, Legal Department
File

1211 W. Sunshine

P04 9037040

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED—
NOT FOR INTERNATIONAL MAIL

(See Reverse)

PS Form 3800, Apr. 1976

SENT TO		Jack Webster III, Pres.
STREET AND NO.		2400 E. Bennett
P.O. STATE AND ZIP CODE		Springfield, MO 65804
POSTAGE		\$
CONSULT POSTMASTER FOR FEES		
OPTIONAL SERVICES		
RETURN RECEIPT SERVICE		
SHOW TO WHOM, DATE AND ADDRESS OF DELIVERY		
SHOW TO WHOM, DATE AND ADDRESS OF DELIVERY WITH RESTRICTED DELIVERY		
SHOW TO WHOM, DATE AND ADDRESS OF DELIVERY WITH RESTRICTED DELIVERY		
TOTAL POSTAGE AND FEES		\$
POSTMARK OR DATE		

PS Form 3811, Apr. 1977

1. The following service is requested (check one).
☒ Show to whom and date delivered.
☐ Show to whom, date, and address of delivery.
☐ RESTRICTED DELIVERY
☐ RESTRICTED DELIVERY
☐ RESTRICTED DELIVERY
 Show to whom, date, and address of delivery. \$
 (CONSULT POSTMASTER FOR FEES)

2. ARTICLE ADDRESSED TO:
 Jack Webster III, President
 Webster Companies
 2400 E. Bennett, Spfld., MO 65804

3. ARTICLE DESCRIPTION:
 REGISTERED NO. P04 9037040 CERTIFIED NO. INSURED NO.

(Always obtain signature of addressee or agent)
 I have received the article described above.
 SIGNATURE [Signature] AUTHORIZED AGENT

4. DATE OF DELIVERY POSTMARK

5. ADDRESS (complete only if requested)

6. UNABLE TO DELIVER BECAUSE: INITIALS

RETURN RECEIPT, REGISTERED, INSURED AND CERTIFIED MAIL

★GPO: 1977-0-249-595

February 13, 1984

Certified No. PO4 9037040

Mr. Jack Webster III, President
Webster Companies
2400 East Bennett
Springfield, Missouri 65804

Re: Harold Peck's 66
1211 W. Sunshine

Dear Mr. Webster:

On Tuesday, September 27, 1983, personnel from the City of Springfield's Water Pollution Control Section, Surveillance and Enforcement Branch, received a report of flammable hydrocarbon products entering the City's sanitary sewer system in the 1600-1800 block of South Fort. The hydrocarbon products were traced to Harold Peck's 66 service station at 1211 W. Sunshine. The tanks and fuel lines are owned by Webster Companies. You had the fuel lines and tanks tested as the City requested by Stoddard Equipment Company. As you know, leaks were found in the west regular storage tank, the no lead product line and the diesel vent line.

The ordinances of the City of Springfield provide for the recovery of the costs involved in the abatement of a violation under emergency conditions. By means of a copy of this letter, these costs are being certified to the Director of Finance as true and accurate costs incurred by the City of Springfield.

Attached to this letter is a detailed explanation of the costs incurred by the Water Pollution Control Section in the detection, monitoring, and treatment of flammable hydrocarbon products that have entered the City of Springfield's sanitary sewer system to November 29, 1983. Payment of these costs should be made to the City of Springfield, and sent to:

City of Springfield
City Hall, Room 210
830 Boonville
Springfield, MO 65802
Attention: Mr. Robert Schaefer

1211 W. Sunshine

WATER AND SEWER COSTS:

September 27, 1983 to November 29, 1983

Water - 4560 ccf	1,922.55
Sewer - 4560 ccf @ .46/ccf	2,097.60
" - (Basic customer charge)	6.04

PERSONNEL COSTS: Surveillance & Enforcement

September 27, 1983 to November 29, 1983

	Burden Rate	Overtime Rate	Time at Site	Costs
Chandler	14.39		31.75	456.88
"		21.58	44.00	949.52
Corson	17.23		13.25	228.29
Pabst	17.23		5.25	90.46
Slaughter	14.39		.50	7.20
Short	14.39		.50	7.20

EQUIPMENT COSTS

Flusher (& a crew of 3)	4.5 hrs. @ 69.28/hr.	311.76
P2-15		
P2-22	462 miles @ .35/mi.	<u>161.70</u>
P2-24		

TOTAL COST: \$6,239.20

1211 W. Sunshine

STODDARD EQUIPMENT CO.

LP Gas and Service Station Equipment

Sales and Service

3536 E. SUNSHINE SPRINGFIELD, MISSOURI 65804

Nov. 22, 1983

Department of Public Works
Attn: Karen A. Chandler
830 Boonville Ave
Springfield, Mo. 65802

Dear Ms. Chandler

This letter is to certify that we have tested and repaired leaks at the Phillips Service Station at Sunshine and Fort streets.

Our initial tests found leaks in the west 4,000 gallon regular storage tank, the no lead product line, and the diesel vent line. All other lines and tanks checked OK at 4 p.s.i. on tanks and vent lines and 70 p.s.i. on product lines.

We, at the expense of Webster Oil Co. replaced the regular and no lead product lines complete and replaced the west regular tank. Webster Oil Co. decided to replace the regular product line even though it did not leak to insure a future problem of this same type would not occur due to the line being of same age as the ones that failed.

All new lines and the tank were air tested and inspected by the local Fire Marshals after installations were completed.

If I can be of any further help, feel free to call.

Sincerely

W.O. Hawkins Jr.

W.O. Hawkins, Jr.
Assistant Manager

cc Jack Webster III
Bob Boyar

1211 W. Sunshine

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE _____ 1-9-84 _____

DEPARTMENT _____

Re: Gasoline in the Sanitary Sewer at Fort Ave. and University St.

At approximately 6:15PM (January 7, 1984) I was paged by the Fire Dept. They informed me that Mrs. Green, at 1128 W. University, had just called in a complaint about a gasoline smell in her house.

I arrived at Mrs. Green's at 6:30 P.M. and she informed me that the smell was not in her house but that her paper boy told her that he could smell a strong gasoline odor in the neighborhood. Mrs. Green contacted the Fire Dept. to be on the safe side.

When Fire Marshal Jim Dancy arrived he checked the following M.H.'s with these results:

Wye Map T-8	
M.H. 18	0% L.E.L.
M.H. 17	10% L.E.L.
M.H. 21	0% L.E.L.
M.H. 12	8% L.E.L.

We returned to Mrs. Green's house to inform her of our findings. We also told her that there was no explosion hazard and that I would check the M.H.'s again on January 8, 1984.

On Sunday, January 8, 1984, I checked the following M.H.'s and obtained these readings:

Wye Map T-8	
M.H. 18	0% L.E.L.
M.H. 17	8-9% L.E.L.
M.H. 21	0% L.E.L.
M.H. 12	10% L.E.L.

Since I did not receive any reading that was higher than 10% I did not ventilate the manholes or flush any lines.

SIGNED _____

Gene

1211 W. Sunshine

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF Office

DATE 12-8-83

DEPARTMENT _____

At approximately 3:00 P.M.

I checked the 1st three man-
holes ~~South~~ ^{North} of Sunshine on
Fort Street. The L.E.L.'s were
100%, 50%, 50% respectively.

SIGNED

J.D. Slaughter
1730 S. Glenstone

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE _____ December 7, 1983 _____

DEPARTMENT _____

An addendum to memo to Bill Crossland of 11-23-83
Re: Gasoline in sewer at Fort and Sunshine

Wednesday, November 23, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:30 p.m.	Stanford	22	0
	University	17	5
	"	18	<10
	Fort	12	0
	"	21	0

Gene and I picked up the fire hose and stand.

Friday, November 25, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:40	Stanford	22	0
	University	17	10
	"	18	0
	Fort	12	0
	"	21	2-3
1:15	Stanford	22	0
	University	17	17
	"	18	0
	Fort	12	0
	"	21	10

Sunday, November 27, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
12:00 p.m.	Stanford	22	0
	University	17	10
	"	18	15
	Fort	12	0
	"	21	0

It rained Saturday evening & Sunday day.

Monday, November 28, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:30 p.m.	Stanford	22	0
	University	17	0
	"	18	0
	Fort	12	7
	"	21	0

I called Sharon Jones to tell her that the fire marshall would give her 30 days to get her tanks and lines checked after he sent his letter.

SIGNED _____

1211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF FILE

DATE December 7, 1983

DEPARTMENT _____

Tuesday, November 29, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:30 a.m.	Stanford	22	0
	University	17	5
	"	18	5
	Fort	12	0
	"	21	0

Wednesday, November 30, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
1:45 p.m.	Stanford	22	0
	University	17	10
	"	18	15
	Fort	12	0
	"	21	0

Joe Montgomery of Montgomery Metalcraft called about Taylor Petroleum. He had several Petrotite tests to perform and he was trying to schedule the different businesses. Bill Crossland said he would write his letter to Taylor Petroleum this week.

Thursday, December 1, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:00 a.m.	Stanford	22	0
	University	17	<5
	"	18	<10
	Fort	12	2
	"	21	<5

Friday, December 2, 1983


<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:30 a.m.	Stanford	22	0
	University	17	11
	"	18	12
	"	19	10
	Fort	12	0
	"	21	0-2
	Storm Sewer		0

Monday, December 5, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:15	Stanford	22	0
	University	17	25
	"	18	0
	Fort	12	0
	"	21	0

Gene and I closed the cover of manhole 21 on Fort Street.

cc: Bob Schaefer, P.E., Supt. of Sanitary Services
 Henry Cole, P.E., Sanitary Engineer
 Greg Perkins, Dept. of Natural Resources
 File


 Karen Chandler
 SIGNED _____
 Water Pollution Control Inspector III
 Surveillance & Enforcement
 1211 W. Sunshine

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF Bob Schaefer
DEPARTMENT SANITARY SERVICES

DATE 11-29-83

This is an estimate of the cost of the gasoline in the sewer problem at Fort and Sunshine.

Water	\$1,954.95
Sewer	2,278.50

Personnel - Time		
Chandler	31.25 hrs. (regular)	\$ 449.69
	44.00 hrs. (x 1½ time)	949.74
Corson	11.75	202.45
Pabst	5.25	90.46
Lyman	1.00	17.23
Slaughter	.50	7.20
Short	.50	7.20
		<u>\$1,723.97</u>

Equipment		
Flusher + a crew of 3	4½ hrs. @ 69.28/hr.	311.76
P2-15		
P2-22	462 miles @ .35/mi.	161.70
P2-24		

Total Cost	<u>\$6,430.88</u>
------------	-------------------

cc: File

Karen Chandler
Water Pollution Control Inspector II
SIGNED Surveillance & Enforcement

1211 W. Sunshine

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF Bill Crossland
DEPARTMENT Fire Marshal

DATE 11-23-83

Re: Gasoline in sewer at Fort and Sunshine

This is the information that you requested about the gasoline problem at Fort and Sunshine. Our readings for November 22, 1983 were:

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:50 a.m.	Stanford	22	10
	University	17	10
	"	18	0
	Fort	12	25
	"	21	<5
3:15 p.m.	Stanford	22	0
	University	17	10
	"	18	0
	Fort	12	5
	"	21	0

Our readings for November 23, 1983 were:

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
11:00 a.m.	Stanford	22	0
	University	17	10
	"	18	20
	Fort	12	0
	"	21	0

The resident at 1730 South Fort complained of a gasoline odor in her house. It was coming from the basement where water was running in through the wall. The explosion meter read 2% of L.E.L.

Because we are still experiencing a problem in this area, we would like for you to have Taylor Petroleum at 1201 W. Sunshine test their lines and tanks. Their home office address is:

Taylor Petroleum, Inc.
Box 3430
Amarillo, Texas 79106

Sharon Jones, the manager of Taylor Petroleum, called me on November 23, 1983, at 2:15 p.m. to ask about having her tanks checked. She said that Harold Peck told her that he had lost 44,000 gallons of fuel. She said that it would be better to send your letter to her instead of the home office.

cc: Bob Schaefer, P.E., Superintendent of Sanitary Services
Henry Cole, P.E., Sanitary Engineer
Greg Perkins, Department of Natural Resources
File

SIGNED Karen Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

1211 W. Sunshine

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE _____ 11-7-83 _____

DEPARTMENT _____

On Tuesday, September 27, 1983, Bill West reported a strong gasoline odor in the sewer at Fort and Stanford. The explosion meter read 100% of L.E.L. at manhole 12 and 30% of L.E.L. at manhole 22 on Fort Street. Various other manholes were checked visually and with the meter in order to determine the source of the leak. The results were:

<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
Sunshine	1	0
University	17	5
"	18	0
"	19	0
Stanford	27	0
Fort	21	5

Harold Peck, of Harold Peck's Phillips 66 station at 1211 W. Sunshine, said that last week he had noticed they were pumping air through the dispensers on the regular pumps. David Reeves, of Stoddard Equipment, said they had tested the regular line Monday and it wouldn't hold pressure. The line was rubber and had been in the ground 15-20 years. Stoddard found a hole in the line to the regular pump and they replaced that section of the line. On Tuesday they air tested the line again and for 4½ hours at 60 lbs. of pressure, and it didn't lose a pound of pressure.

Omer Boyce flushed the lines that run into manhole 12 on Fort Street twice. The night crew flushed these lines once each shift. The covers on manholes 12 and 22 on Fort Street were left off overnight to vent off the gasoline vapors.

Wednesday, September 28, 1983:

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:00 a.m.	Fort	12	20
3:00 p.m.	"	12	100

Omer Boyce flushed the lines going into manhole 12 on Fort and the night crew flushed these lines once each shift.

Thursday, September 29, 1983:

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:00 a.m.	Fort	12	15
1:30 p.m.	"	12	100
2:30 p.m.	"	12	100

Fire Marshall Dave Wilson also got 100% of L.E.L. at manhole 12 at 2:30 p.m. I met with Ray Toates of City Utilities to borrow a water meter so that we can flush the line continuously from the fire hydrant east of manhole 19 on west University Street. Gene Pabst, J.D. Slaughter and I set up the fire hoses and began flushing the line. The City Utilities meter is a Worthington-Gamon meter. The beginning reading was 0000740cf.

I asked Harold Peck to have all of the tanks and lines tested. He said he would call the owner (Webster Oil Company) in the morning and have it done. The manager at Taylor Express Mart at 1201 West Sunshine was gone for the day and I was unable to talk to her at this time.

SIGNED _____

1211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE 11-7-83 _____

DEPARTMENT _____

Mrs. Deeds, at 1650 S. Fort, had called to report a gasoline odor in her bathroom, but it was gone when I got there. She told me that she had smelled the odor on and off since July.

I called the telephone company to report that we had gasoline in the sewer and probably in the ground because they have buried cables in this area.

Friday, September 30, 1983:

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
5:00 p.m.	Fort	12	30
	"	17	40
	"	21	20

I talked to Bob Boyar of Webster Oil Companies and he said he would have the tanks and lines tested on Monday. The residents of 1754 S. Fort complained of a gasoline odor in their house, so I asked Ralph Whitworth to flush the line between manholes 17 and 21 on Fort.

Saturday, October 1, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
8:30 a.m.	University	17	50
	"	18	<10
	Fort	12	40

I asked Gerald Noblett to have a crew flush between manholes 17 and 21 on Fort and opened up the cover of manhole 21 to allow the gasoline vapors to vent off.

Sunday, October 2, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:30 p.m.	University	17	30
	Fort	12	30
	"	21	50

Monday, October 3, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:00 a.m.	Stanford	22	10
	Fort	12	30
	"	21	40
	University	17	15

Fire Marshall Jim Dancy also called Bob Boyar over the weekend and asked him to have all the lines and tanks tested.

I talked to Sharon Jones, the manager at Taylor Express Mart (Taylor Petroleum), and she hasn't noticed any product loss. They have three tanks: regular, no lead, and premium. The regular tank was put in about a year ago and holds 8,000 gallons of gasoline. There is an abandoned tank on the west side of her property. The tank had about 1" of water in the bottom of it and 100% of L.E.L. on the explosion meter. I told her she needed to contact a fire marshall to find out the procedure for abandoning a tank.

SIGNED _____

1211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____


DATE 11-7-83 _____

DEPARTMENT _____

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:30 p.m.	Fort	21	15

One of the residents in the house at 1754 S. Fort said the odor wasn't as strong in the house.

One of the Stoddard Equipment operators said it might be two or three days before they would have any results as the cement on the top of the tanks had to be jack-hammered off.



Tuesday, October 4, 1983

It rained all night.

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:30 a.m.	Fort	12	80
"	"	21	50
2:45	Stanford	22	0
	Fort	12	25
	"	21	5

It started raining again about 2:30 p.m.

Wednesday, October 5, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:40 a.m.	Stanford	22	10
	Fort	12	40
	"	21	5

The siphon birdge between the two regular tanks was a rubber hose. There were no apparent leaks in the hose but Stoddard Equipment replaced it.

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:00 p.m.	Stanford	22	5
	University	17	0
	Fort	12	80
	"	21	0

I gave Dave Reeves of Stoddard Equipment my card and asked him to send me the results of his tests when he's done.

Thursday, October 6, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:00 a.m.	Stanford	22	40
	University	17	50
	Fort	12	75
	"	21	50

Dave Reeves said they put pressure on one of the regular lines last night and it didn't hold. He wasn't sure if the problem was in the tank or the vent line.

SIGNED _____

1211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF FILEDATE 11-7-83

DEPARTMENT _____

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:00	Stanford	22	0
	Fort	12	60

I called Jim Dancy about an interceptor trench, but he said the fire department couldn't make that kind of recommendation.

Friday, October 7, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
11:00 a.m.	Stanford	22	0
	University	17	35
	Fort	12	30
	Fort	21	35

Dave Reeves said that the diesel tank wouldn't hold pressure, but sticking the tank didn't indicate a product loss.

12:00 p.m. Bob Boyar went to the station to shut down all of the dispensers and I met with him at this time. I reminded him that Webster Oil Company was liable for any problems caused by hydrocarbon products in the sewer and recommended that he build an interceptor trench with a recovery well and gave him a copy of the section on interceptor trenches in Chapter V "Clean-Up Techniques" in the Underground Spill Cleanup Manual published by the American Petroleum Institute. At this time, he said that he would dig a trench and that he might get rid of the tanks altogether. He didn't know how much product had been lost.

4:00 p.m. I called Bob Boyar at work and he said that he was having all of the gasoline removed from the tanks, while Stoddard Equipment finished testing them. At this time he said he wouldn't dig a trench, but would take core samples.

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:30 p.m.	Stanford	22	0
	University	17	20
	Fort	12	0
	"	21	45

Saturday, October 8, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:30 p.m.	Standord	22	0
	University	17	20
	Fort	12	30
	"	21	15

Sunday, October 9, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
7:00 p.m.	Stanford	22	0
	University	17	15
	Fort	12	15
	"	21	15

SIGNED _____

1211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE 11-7-83 _____

DEPARTMENT _____

Monday, October 10, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:30 a.m.	Stanford	22	0
	University	17	30
	"	18	0
	Fort	12	10
	"	21	30

2:30 p.m. The diesel tank wasn't leaking, the leak was in the vent line, they were still testing the regular tanks.

Tuesday, October 11, 1983

Dave Reeves of Stoddard Equipment said that the west regular tank wouldn't hold pressure. This tank was buried in lime chat which is very corrosive. The no lead line wouldn't hold pressure. Dave said they would replace all of the lines, replace or abandon the regular tank and the service station would probably be back in business by the weekend.

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:00 p.m.	Stanford	22	40
	University	17	30
	"	18	0
	Fort	12	40
	"	21	25

It started raining hard shortly after 4:00 p.m.

Wednesday, October 12, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:00 p.m.	Stanford	22	15
	University	17	5
	Fort	12	15
	"	21	<5

Stoddard Equipment was replacing all of the lines.

Thursday, October 13, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
11:00 a.m.	Stanford	22	0
	University	17	25
	"	18	100
	Fort	12	<5
	"	21	5
	Sunshine	45	0
	"	19	0
	"	19a	0

Friday, October 14, 1983

<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
Stanford	22	0
University	17	40
"	18	0
Fort	12	20
"	21	35

SIGNED _____

1211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE 11-7-83

DEPARTMENT _____

Dave Reeves of Stoddard Equipment said that new fuel lines were pressure tested section by section and the Fire Department inspected the lines.

Saturday, October 15, 1983

<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
Stanford	22	0
University	17	40
"	18	0
Fort	12	35
"	22	35

Sunday, October 16, 1983

<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
Stanford	22	30
University	17	30
"	18	0
Fort	12	50
"	21	0

It rained all night and day.

Monday, October 17, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:30 a.m.	Stanford	22	0
	University	17	50
	"	18	0
	Fort	12	50
	"	21	25

Tuesday, October 18, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
1:30 p.m.	Stanford	22	0
	University	17	50
	"	18	0
	Fort	12	50
	"	21	25

I talked to Bob Boyar on the phone. He said they lost approximately 800 gallons of product. I recommended that he report the loss to the Missouri Department of Natural Resources.

At this time he thought he would abandon the leaking tank, and I advised him to contact the fire marshall about the procedure.

They were waiting for an agent from Phillips 66 to inspect the station and advise them about clean up procedure.

SIGNED _____

1211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF FILEDATE 11-9-83

DEPARTMENT _____

Wednesday, October 19, 1983

<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
Stanford	22	<5
University	17	35
"	18	0
Fort	12	50
"	21	20

Thursday, October 20, 1983

<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
Stanford	22	<5
University	17	35
"	18	0
Fort	12	35
"	21	35

I sent a letter to Bob Boyar, of Webster Petroleum, requiring them to dig a trench by November 1, 1983.

Friday, October 21, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
5:45 p.m.	Stanford	22	0
	University	17	5
	"	18	100
	Fort	12	0
	"	21	0

I reported the 100% of L.E.L. in manhole 18 to the Fire Department.

Saturday, October 22, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:30 p.m.	Stanford	22	0
	University	17	30
	"	18	5
	Fort	12	0
	"	21	<10

Sunday, October 23, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:30 p.m.	Stanford	22	0
	University	17	15
	"	18	0
	Fort	12	0
	"	21	<5

SIGNED _____

1211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF FILEDATE 11-9-83

DEPARTMENT _____

Monday, October 24, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:30 a.m.	Stanford	22	0
	University	17	15
	"	18	0
	Fort	12	0
	"	21	<10

Turned off water, the meter read 0431810

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:00 p.m.	Stanford	22	0
	University	17	5
	"	18	0
	Fort	12	0
	"	21	5

Tuesday, October 25, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:30 a.m.	Stanford	22	<5
	University	17	20
	"	18	0
	Fort	12	10
	"	21	0
3:15 p.m.	Stanford	22	<5
	University	17	<10
	"	18	0
	Fort	12	<15
	"	21	0

Wednesday, October 26, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:00 p.m.	Stanford	22	0
	University	17	<5
	"	18	45
	Fort	12	<5
	"	21	0

Thursday, October 27, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:30 a.m.	Stanford	22	0
	University	17	30
	"	18	0
	Fort	12	0
	"	21	20

SIGNED _____

(211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE 11-9-83

DEPARTMENT _____

I talked to Bob Boyar, of Webster Oil Company, on the phone to see if he had any questions about my letter. He said he will dig an interceptor trench Monday or Tuesday. His estimate of product loss was between 700-800 gallons. He said that Harold Peck owned that gasoline and didn't keep complete inventory records. Bob said that in the future he will check the records twice a week.

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:00 p.m.	Stanford	22	15
	University	17	<45
	"	18	10
	Fort	12	0
	"	21	0

Water was turned on again. The resident of 1736 S. Fort said she could smell gasoline in her house at times, particularly at night.

Friday, October 28, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
11:00 a.m.	Stanford	22	0
	University	17	15
	"	18	20
	Fort	12	0
	"	21	<5

Saturday, October 29, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
5:30 p.m.	Stanford	22	<15
	University	17	10
	"	18	0
	Fort	12	10
	"	21	10

Monday, October 31

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:15 a.m.	Stanford	22	10
	University	17	10
	"	18	0
	Fort	12	5
	"	21	<10
3:00 p.m.	Stanford	22	10
	University	17	15
	"	18	0
	Fort	12	20
	"	21	15

Stoddard Equipment started their trench. At the deepest spot, approximately 13 ft. down, there was a weak gasoline odor and the dirt was damp looking.

SIGNED _____

1211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE 11-22-83

DEPARTMENT _____

Tuesday, November 1, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:45 a.m.	Stanford	22	<5
	University	17	15
	"	18	0
	Fort	12	5
	"	21	5

Stoddard Equipment finished the trench. Two wells were installed, one at the west end of the trench where the depth is approximately 7 feet, and the other is at the deepest part of the trench, approximately 13 feet deep. The trench is uneven, due to the rock layer. It rained all day and night.

Thursday, November 3, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:00 p.m.	Stanford	22	0
	University	17	5
	"	18	0
	Fort	12	0
	"	21	0

Rained all evening.

Friday, November 4, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:00 a.m.	Stanford	22	0
	University	17	5
	"	18	0
	Fort	12	5
	"	21	0

The residents at 1730 S. Fort complained of a gasoline odor in the basement on Thursday night. Omer Boyce flushed the line and said he had run into an obstruction. There was no gasoline odor in the house this morning. I turned the hydrant off (reading 0447850).

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
11:30 a.m.	Fort	12	25
	University	17	15
	"	18	0

I turned the hydrant on again.

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:00 p.m.	Stanford	22	20
	University	17	15
	"	18	5
	Fort	12	25
	"	21	15

SIGNED _____

1211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE 11-22-83

DEPARTMENT _____

Saturday, November 5, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:00 p.m.	Stanford	22	5
	University	17	5
	"	18	0
	Fort	12	0
	"	21	5

Sunday, November 6, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:00 p.m.	Stanford	22	5
	University	17	10
	"	18	0
	Fort	12	0
	"	21	10

Monday, November 7, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:00 p.m.	Stanford	22	<5
	University	17	15
	"	18	0
	Fort	12	0
	"	21	<5

Stoddard Equipment began digging up the old tank.

Tuesday, November 8, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
9:20 a.m.	Stanford	22	0
	University	17	5
	"	18	0
	Fort	12	0
	"	21	5

I turned off the fire hydrant (reading 0454390)

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:00 p.m.	Stanford	22	0
	University	17	15
	"	18	0
	Fort	12	5
	"	21	10

Stoddard had the old tank out. There was a gasoline odor in the pit where the tank had been. There appeared to be a piece of clay tile on the west side of the pit.

Wednesday, November 9, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:30 p.m.	Stanford	22	0
	University	17	15
	"	18	15
	"	19	10
	Fort	12	0
	"		

SIGNED _____

21

0
1211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE 11-22-83 _____

DEPARTMENT _____

Stoddard Equipment put the new tank in.

Thursday, November 10, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:45 a.m.	Stanford	22	0
	University	17	10
	"	18	20
	"	19	<10
	Fort	12	0
	"	21	0

Friday, November 11, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:15 p.m.	Stanford	22	0
	University	17	10
	"	18	0
	"	19	0
	Fort	12	0
	"	21	10

Saturday, November 12, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:15 p.m.	Stanford	22	0
	University	17	<10
	"	18	0
	"	19	0
	Fort	12	0
	"	21	10

Sunday, November 13, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
1:00 p.m.	Stanford	22	0
	University	17	<25
	"	18	0
	"	19	0
	Fort	12	0
	"	21	10

The batteries in the explosion meter were weak.

Monday, November 14, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:45 p.m.	University	17	15
	"	18	0
	Fort	12	20
	"	21	<10

We removed hose and stand.

SIGNED _____

1211 W. Sunshine

CITY OF SPRINGFIELD

INTER-OFFICE MEMORANDUM

ATTENTION OF FILEDATE 11-22-83

DEPARTMENT _____

Tuesday, November 15, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
4:15 p.m.	University	17	5
	"	18	10
	Fort	12	0

Friday, November 18, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
3:30 p.m.	Stanford	22	15
	University	17	30
	"	18	0
	"	19	0
	Fort	12	0
	"	21	15

Bob Corson and I set up the meter and fire hose again and started flushing. Beginning reading was 0481710. Mrs. Green at 1128 University complained about the hose being set up again.

Saturday, November 19, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
2:00 p.m.	Stanford	22	5
	University	17	10
	"	18	0
	"	19	0
	Fort	12	5
	"	21	10

Sunday, November 20, 1983

Meter not working.

Monday, November 21, 1983

<u>Time</u>	<u>Street</u>	<u>MH#</u>	<u>% of L.E.L.</u>
10:35	Stanford	22	0
	University	17	< 10
	"	18	0
	"	19	0
	Fort	12	0
	"	21	< 10

Gene Pabst and I turned the meter off again. Ending reading 0484020.

SIGNED

Karen Chandler
1211 W. Sunshine

K.C.

NOV 21 1983

PS Form 3811, Apr. 1977

RETURN RECEIPT, REGISTERED, INSURED AND CERTIFIED MAIL

1. The following service is requested (check one). <input checked="" type="checkbox"/> Show to whom and date delivered <input type="checkbox"/> Show to whom, date, and address of delivery <input type="checkbox"/> RESTRICTED DELIVERY <input type="checkbox"/> RESTRICTED DELIVERY <input type="checkbox"/> RESTRICTED DELIVERY Show to whom, date, and address of delivery, \$ (CONSULT POSTMASTER FOR FEES)	
2. ARTICLE ADDRESSED TO: Robert Boyar, Webster Companies 2400 E. Bennett Springfield, MO 65804	
3. ARTICLE DESCRIPTION: REGISTERED NO.	CERTIFIED NO. INSURED NO.
(Always obtain signature of addressee or agent) I have received the article described above. SIGNATURE <input checked="" type="checkbox"/> Addressee <input type="checkbox"/> Authorized agent	
4. DATE OF DELIVERY NOV 18 1983	POSTMARK
5. ADDRESS (Complete only if requested)	
6. UNABLE TO DELIVER BECAUSE:	CLERK'S INITIALS

 P04 9037038
 RECEIPT FOR CERTIFIED MAIL

 NO INSURANCE COVERAGE PROVIDED—
 NOT FOR INTERNATIONAL MAIL
 (See Reverse)

PS Form 386, Apr. 1976

SENT TO	
Robert Boyar	
STREET AND NO.	
2400 E. Bennett	
P.O. STATE AND ZIP CODE	
Springfield, MO 65804	
POSTAGE	\$
CERTIFIED FEE	\$
SPECIAL DELIVERY	\$
RESTRICTED DELIVERY	\$
RETURN RECEIPT SERVICE	
SHOW TO WHOM AND DATE DELIVERED	\$
SHOW TO WHOM, DATE AND ADDRESS OF DELIVERY	\$
SHOW TO WHOM AND DATE DELIVERED WITH RESTRICTED DELIVERY	\$
SHOW TO WHOM, DATE AND ADDRESS OF DELIVERY WITH RESTRICTED DELIVERY	\$
TOTAL POSTAGE AND FEES	\$
POSTMARK OR DATE	

November 16, 1983

Certified No. PO4 9037038

Mr. Robert Boyar
Webster Companies
2400 E. Bennett
Springfield, MO 65804

Dear Mr. Boyar:

Due to the large amount of rainfall the city has received in the past month, the two recovery wells that were installed in the interceptor trench at Harold Peck's 66 station at 1211 W. Sunshine have water standing in them. The explosion meter reading in both of these wells is 50% of the Lower Explosion Limit (L.E.L.). It is important to pump out these wells occasionally or the hydrocarbon product will move to the ends of the ditch, pass around the impermeable barrier and enter the city's sanitary sewer system.

It is our recommendation that you check these wells at least twice a month. When water is standing in the wells they should be pumped out with an explosion-proof pump and the hydrocarbon product skimmed off for disposal in an approved manner.

If you have any questions, please don't hesitate to call 864-1924.

Yours truly,

Karen Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

KC:js

cc: Robert R. Schaefer, P.E., Superintendent of Sanitary Services
Henry Cole, P.E., Sanitary Engineer
Greg Perkins, Department of Natural Resources
Dale Bittle, Chief Fire Marshall
File

1211 W. Sunshine

SENDER: Complete items 1, 2, and 5. Add your address in the "RETURN TO" space on reverse.

1. The following service is requested (check one).
☒ Show to whom and date delivered.
☐ Show to whom, date, and address of delivery.
☐ RESTRICTED DELIVERY.
☐ RESTRICTED DELIVERY.
 Show to whom and date delivered.
☐ RESTRICTED DELIVERY.
 Show to whom, date, and address of delivery. \$
 (CONSULT POSTMASTER FOR FEES)

2. ARTICLE ADDRESSED TO:
 Robert Boyar
 2400 E. Bennett
 Springfield, MO 65804

3. ARTICLE DESCRIPTION:
 REGISTERED NO. P04 9037167 CERTIFIED NO. INSURED NO.

(Always obtain signature of addressee or agent)

I have received the article described above.
 SIGNATURE ☐ Addressee ☐ Authorized agent

4. DATE OF DELIVERY

5. ADDRESS (Complete only if requested)

6. UNABLE TO DELIVER BECAUSE:

CLERKS
INITIALS

PS Form 3811, Apr. 1977 RETURN RECEIPT, REGISTERED, INSURED, AND CERTIFIED MAIL

P04 9037167

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED—
 NOT FOR INTERNATIONAL MAIL
 (See Reverse)

SENT TO
 Mr. Robert Boyar
 STREET AND NO.
 2400 E. Bennett
 P.O. STATE AND ZIP CODE
 Springfield, MO 65804

POSTAGE \$

CERTIFIED FEE

SPECIAL DELIVERY

RESTRICTED DELIVERY

SHOW TO WHOM AND DATE DELIVERED

SHOW TO WHOM, DATE, AND ADDRESS OF DELIVERY

SHOW TO WHOM AND DATE DELIVERED WITH RESTRICTED DELIVERY

SHOW TO WHOM, DATE AND ADDRESS OF DELIVERY WITH RESTRICTED DELIVERY

CONSULT POSTMASTER FOR FEES

OPTIONAL SERVICES

RETURN RECEIPT SERVICE

TOTAL POSTAGE AND FEES \$

POSTMARK OR DATE

PS Form 3800, Apr. 1976

October 20, 1983

Mr. Robert Boyar
Webster Companies
2400 E. Bennett
Springfield, MO 65804

Dear Mr. Boyar:

As you know, for the past month the City of Springfield has been experiencing a problem of flammable hydrocarbon products entering its sanitary sewer system in the 1600-1800 block of south Fort, that were traced to a leaking regular tank and gasoline line at Harold Peck's 66 Station at 1211 W. Sunshine. The fuel tanks and lines are owned by Webster Companies. You had the fuel lines and tanks tested as we requested and you replaced all of the fuel lines.

Because we are still detecting dangerously high levels of flammable hydrocarbon products in the sanitary sewer, especially after rainfall events, this department is requiring you to dig an interceptor trench and install a recovery well between Harold Peck's 66 Station and the house at 1754 S. Fort. This should be completed before November, 1983.

Enclosed is a suggested design for the trench and well taken from the American Petroleum Institute's Underground Spill Cleanup Manual.

Due to the nature of the problem, further action may be required to protect the health, life, and property of those affected by the migration of the lost product.

If you have any questions, please don't hesitate to call.

Yours truly,

Karen A. Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

KAC:js

cc: Robert R. Schaefer, P.E., Superintendent of Sanitary Services
Henry Cole, Sanitary Engineer
Greg Perkins, Dept. of Natural Resources
Dale Bittle, Chief Fire Marshall
File

1211 W. Sunshine